



**FIG. 3****FIG. 4**







FIG. 10






FIG. 11



Pillar Mounting Support



Back Load Cell Mounting








FIG. 13



**FIG. 15****FIG. 16****FIG. 17**




FIG. 18




FIG. 19




















FIG. 20

**FIG. 21****FIG. 22****FIG. 23**




**FIG. 25****FIG. 26****FIG. 27****FIG. 28**



**FIG. 29****FIG. 30****FIG. 31****FIG. 32**



**FIG. 33****FIG. 34****FIG. 35****FIG. 36**



**FIG. 37****FIG. 38****FIG. 39**

Ramp and Hinge Assembly

**FIG. 40****FIG. 41****FIG. 42**





**FIG. 47****FIG. 48**




FIG. 49




FIG. 50









FIG. 51

**FIG. 52****FIG. 53****FIG. 54**

**FIG. 55****FIG. 56**




FIG. 57




FIG. 58




FIG. 59




FIG. 60




FIG. 61





FIG. 62



Front View

FIG. 63





This page is not part of
the document!

US2004032609 / 2005-033637

2/2

Date: 2 juin 2005

Recipient: IB

**FIG. 64****FIG. 65****FIG. 66**

Key Pad Connector Outlet

FIG. 67




FIG. 68A




FIG. 68B




FIG. 69




FIG. 70




FIG. 71




FIG. 72




FIG. 73




FIG. 73A




FIG. 73B




FIG. 73C




FIG. 73D




FIG. 76





FIG. 75






FIG. 77




FIG. 78




FIG. 80




FIG. 79

FIG. 82





FIG. 81






FIG. 83





FIG. 84



Weight 28 Kg (61.5 lb)

FIG. 85




FIG. 86




FIG. 87




FIG. 89




FIG. 91




FIG. 92A








FIG. 92B






FIG. 96




FIG. 97




FIG. 98




FIG. 99

FIG. 100




FIG. 101







FIG. 102






FIG. 106




FIG. 107















FIG. 108

**FIG. 109****FIG. 110****FIG. 111**

**FIG. 112****FIG. 113**



**FIG. 116****FIG. 117****FIG. 118****FIG. 119**




FIG. 120




FIG. 121














FIG. 122



**FIG. 127****FIG. 128****FIG. 129****FIG. 131****FIG. 130**

**FIG. 132****FIG. 133****FIG. 134**




FIG. 135




FIG. 136




FIG. 137

















FIG. 138

**FIG. 140****FIG. 151****FIG. 155**

**FIG. 141****FIG. 142****FIG. 143**

**FIG. 144****FIG. 145****FIG. 146****FIG. 147**

**FIG. 148****FIG. 149****FIG. 150**




FIG. 152




FIG. 153






FIG. 154

**FIG. 156****FIG. 157**




FIG. 158




FIG. 159




FIG. 160




FIG. 161




FIG. 162




FIG. 163




FIG. 164




FIG. 165




FIG. 166




FIG. 167A




FIG. 167B




FIG. 168




FIG. 169









FIG. 170

**FIG. 171****FIG. 172****FIG. 173****FIG. 174****FIG. 175**




FIG. 176




FIG. 177




FIG. 178




FIG. 179




FIG. 180




FIG. 181




FIG. 182




FIG. 183










FIG. 184

**FIG. 185****FIG. 186****FIG. 187****FIG. 188****FIG. 189****FIG. 190**




FIG. 191




FIG. 192




FIG. 193




FIG. 194




FIG. 195










FIG. 196

**FIG. 197****FIG. 198****FIG. 199****FIG. 200****FIG. 202****FIG. 203**




FIG. 201

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADED TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER: _____**

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.